

wastewater + stormwater

Post-Construction Stormwater Best Management Practices: Inspection and Compliance Program Overview and Updates

Kirk Lambrecht Division Inspector Division of Environmental Compliance

August 8, 2019



Outline

- BMP Stormwater Program Introduction
- Inspections & Compliance Overview
- Lessons Learned
- Looking Forward





Stormwater BMP Program

- Stormwater BMPs are structural, vegetative, or managerial practices used to treat, prevent, or reduce pollutants in stormwater runoff.
- MSD's BMP program fulfills NPDES Phase II small MS4 requirements to address the quality of stormwater runoff from new and redevelopment projects ≥ 1 acre.
 - Provide water quality treatment for 90% of annual rainfall.
 - Reduce runoff volume to pre-construction levels on new development sites.
 - Channel protection through extended detention (1yr/24hr storm).
 - Stand alone BMPs must remove minimum 80% of TSS and have an acceptable longevity rate.



Stormwater BMP Program

- MSD provides site design guidance, reviews projects, issues permit for construction, inspects and approves construction.
- Following project approval, constructed BMPs are entered into the Inspection and Compliance Program.
 - Field Inspections
 - Annual Reports Due List





Stormwater BMP Program

stormwater

Prior to approving plans the owner enters into a Maintenance Agreement with MSD. The MA includes the following:

- Requires owner to maintain facility in good working order;
- References SWMFR O&M which describes requirements for inspections, maintenance, and reporting;
- Reserve area for each BMP;
- Authority for MSD to make repairs should the owner fail to properly maintain the BMP; and,
- Agreement is to continue in perpetuity.





Stormwater BMP Program

Inspection and Compliance

- BMPs are inspected on a 3 year cycle.
- Informal and Formal Enforcement Actions are taken for facilities in disrepair.
 - O&M Enforcement Response Plan (updated 2019)
- Legal Authority for compliance inspections and enforcements is provided by MSD Ordinances 9030 and 15048.
- Annual report processing and review.
- Program/Technical Assistance


| STORMWATER MANAG | EMENT FACILITY MAINTENANCE | INSPECTION CHECKLIST |
|--|--|---|
| 6 | IOR/BIOS: BIORETENTION/RAIN GAR | IDEN |
| Location: | P Job Number: | |
| Owner Change since last inspection? Yes No | Inspector: | |
| Owner Name: | Date of inspection: | |
| Owner Address: | Owner Phone Number: | |
| Site Conditions: | | |
| | | |
| INSPECTION BATING SYSTEM | | |
| 0 = Good condition. Well maintained, no action required. S | atisfactory Performance. | |
| 1 = Moderate condition. Should monitor. Satisfactory Perfo 2 = Degraded condition. Routine maintenance and repair n | ended Unsalteraciony Performance | |
| 3 = Serious condition. Immediate need for repair or replace | ement, Upsatisfactory Performance. | |
| NOTE TO INSPECTOR: All personnel entering any | contine. Joaces must take appropriate sa | fety measures and follow applicable OSHA regulations. |
| INSPECTION ITEMS | RATING | COMMENTS |
| Overall Drainage Area Conditions: | | |
| A. INLETS (if not piped, identify as overland flow) | 0 1 2 3 N/A | |
| Provide stable conveyance into facility? Excessive trash/debris/sediment accumulation? | 0 1 2 3 N/A | |
| Excessive trasniteonic sediment accumulation / Evidence of erosion? | 0 1 2 3 N/A | |
| B. PRETREATMENT (If applicable) | 10 1 2 3 Max | |
| Excessive trash/debris/sediment accumulation? | 0 1 2 3 N/A | |
| Evidence of standing water? | 0 1 2 3 N/A | |
| (Ponding, Noticeable Odors, Water Stains, Algae) | | |
| Evidence of clogging? | 0 1 2 3 N/A | |
| Dead vegetation/exposed soll? | 0 1 2 3 N/A | |
| Evidence of erosion? C. TREATMENT AREA AND VEGETATION | 0 1 2 3 N/A | |
| | 0 1 2 3 N/A | |
| Excessive trash/debris/sediment accumulation? Signs of erosion or movement of mulch (or pea gravel)? | 0 1 2 3 N/A | |
| Signs of erosion of movement of mulcin (of pea gravel)? Evidence of oll/chemical accumulation? | 0 1 2 3 NA | |
| Evidence of standing water? | 0 1 2 3 NA | |
| (Ponding, Noticeable Odors, Water Stains, Algae) | | |
| Underdrain system (if equipped) broken/clogged? | 0 1 2 3 N/A | |
| Adequate plant covering present? Is vegetation overgrown? Invasive, overgrown weeds, woody | 0 1 2 3 N/A | |
| vegetation overgrown? invasive, overgrown weeds, woody vegetation? | 0 1 2 3 N/A | |
| Dead vegetation/exposed soll? | 0 1 2 3 N/A | |
| Signs of mulch layer thinning (or pea gravel)? | 0 1 2 3 N/A | |
| D. OVERFLOW/OUTLET STRUCTURE | | |
| Stable conveyance out of facility provided? | 0 1 2 3 N/A | |
| Excessive trash/debris/sediment accumulation? | 0 1 2 3 N/A | |
| Evidence of erosion atlaround? E HAZARDS | 0 1 2 3 N/A | |
| E. HAZARDS Complaints from local residents? (describe if any) | 0 1 2 3 N/A | |
| Complaints from local residents? (describe if any) Any public hazards observed? (describe if any) | 0 1 2 3 N/A | |
| F. CORRECTIVE ACTIONS* | 1 | |
| | il correctue actions recommended or com | nieled during inspection |
| "If any 2-3 ratings are given in Sections A-E of this checklist, lis | | |
| CORRECTIVE ACTIONS | OWNER | COMPLETED AT TIME OF INSPECTION |
| | | |
| | | |
| | | |
| | | |
| G. PHOTOGRAPHS | | |
| Please attach photographs, with descriptions, showing current of | condition of the system and any defectenci | es noted in this inspection. |
| | | |

Post-Construction BMPs Built, Permitted for Construction, or Under Review as of 12/31/2018

- 5,012 Total BMPs
- Bioretention (2,496)
- Permeable Pavements (892)
- Other (526, amended soils)




stormwater



MSD Yearly Inspections for 2015-2019

 *1,304 inspections projected for 2019 (787 through July)






MSD Yearly Enforcement Actions 2015-2019

 2019 enforcements (57) represent those taken though July.







stormwater

Most Common Reasons for Enforcement:

- Excess debris or sediment
 - Raingardens, permeable pavements, HDSUs
- Excessive erosion
- Clogging or inadequate drainage
- Invasive plants
- Structural components
 - Permeable pavements with excessive spalling, compaction, or which has been permanently sealed.
 - Missing cleanout caps
 - Broken filter cartridges







Inspection & Compliance

Lessons Learned:

- Install certain BMPs during final phases of construction and protect from construction sediment.
- Maintaining the contributing drainage area can be just as important as the treatment basin.
- Perform regular inspections and maintenance to avoid costly repairs or restoration.







Inspection & Compliance

Looking Ahead:

- The Inspection & Compliance area for Stormwater BMPs will continue to grow.
- Early stages of inspecting aged detention basins and developing I&C program.
 - Nearly 2,800 facilities. Many that were not previously approved by MSD and lack a clear maintenance agreement.
 - Inspections to occur on a five year cycle.
 - Facilities will be inspected for condition and performance. Complaints will be considered as part of the overall assessment.



Questions?





wastewater + stormwater

Kirk Lambrecht, Division Inspector Division of Environmental Compliance Phone: (314) 436-8758 Email: klambrecht@stlmsd.com